



Is a Generic Part Worth the Cost?

Here are the facts: A Bakers Pride Super Deck 6 Gas Pizza Series Deck Oven (Y-600) costs about \$12,300. The oven needs a new temperature probe, which controls the heat source in the oven. Generic parts can be less expensive, but **could** cause the oven to malfunction, overheat or worse. Let's add up the costs if the generic temperature probe fails.



Real OEM Bakers Pride Temperature probe: **\$375**

Generic Temperature probe: **\$362.09**

Cost difference: **\$12.91**

Let's Do the Math!



Here's what it costs if a generic temperature probe fails:



Real OEM Bakers Pride Temperature probe:

\$375

Labor costs for service technician

\$200-600 per visit*

Real OEM Part Total **\$575-\$975**

Generic Temperature probe:

\$362.09

New Burner

\$879.45

Bad temperature control can cause the burner to degrade prematurely

New Thermopile

\$99.09

Labor costs for service technician

\$200-600 per visit*

Bakers Pride T1118Y Baking Deck

\$1,410.20

Using a bad thermostat can degrade the oven deck

Another service call

\$200-600 per visit*

Generic Part Total **\$3,150.83-\$3,950.83**



*labor costs vary by region

Additional Potential Costs of Using Generic Parts



Equipment warranty is now void, all costs out of pocket



Medical expenses if employee or customer gets hurt



Wasted product



Replacing the entire oven when damaged beyond repair



Saving \$12.91 may seem like a good idea now, but is it really worth risking your team and maybe your entire business? We don't think so. You'll always win with genuine OEM and that's the Real truth.