



## Parts and Accessories Diagram

### Model HBB250-UK

**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.


### Replacement Parts




 <p>Hamilton Beach 4421 Waterfront Drive Glen Allen, VA 23060</p>	Revision Description:	Create New CARE Part				Rev. Date:
	Request #:	DOC10882	Page:	1 of 5	Document #:	540005800
						Rev: <b>D</b>

## Parts and Accessories Diagram Model HBB250-UK

**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.





 4421 Waterfront Drive Glen Allen, VA 23060	Revision	Create New CARE Part				Rev. Date:
	Description:					03/23/2020
Request #:	DOC10882	Page:	2 of 5	Document #:	540005800	Rev: <b>D</b>


## Parts and Accessories Diagram

### Model HBB250-UK

**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.

### Accessories




 4421 Waterfront Drive Glen Allen, VA 23060	Revision	Create New CARE Part				Rev. Date:	
	Description:					03/23/2020	
Request #:	DOC10882	Page:	3 of 5	Document #:	<b>540005800</b>	Rev:	<b>D</b>

## Parts and Accessories Diagram Model HBB250-UK

**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.

### Cutter Assembly Replacement Instructions



**Cutter Repair Kit  
for Rio Blenders**




#### **⚠ WARNING**



**Cut Hazard**  
Handle cutter  
assembly with  
care.  
Failure to follow  
these instructions  
can result in cuts  
or other injuries.

#### Removing the old cutter assembly




Hold the blades with a cloth. Unscrew the clutch counterclockwise.




Remove the clutch and felt washer.




Remove the shaft and blade assembly



Use a flathead screwdriver to flatten the tabs on the tab washer.



Remove the nut by turning counterclockwise by hand. Then remove the tab washer and pressure washer.



Remove bushing.


<p>4421 Waterfront Drive Glen Allen, VA 23060</p>	Revision Description:	Create New CARE Part			Rev. Date:
	Request #:	DOC10882	Page:	4 of 5	03/23/2020
				Document #:	<b>540005800</b>
				Rev:	<b>D</b>

## Parts and Accessories Diagram


### Model HBB250-UK

**PROPRIETARY RIGHTS NOTICE** This document and all information contained within it is the property of Hamilton Beach Brands, Inc. (HBB). It is confidential and proprietary and has been provided to you for a limited purpose. It must be returned or destroyed upon request. Disclosure, reproduction or use of this document and any information contained within it, in full or in part, for any purpose is forbidden without the prior written consent of HBB. No photographs may be taken of any article fabricated or assembled from this document without the prior written consent of HBB.


**Installing the new cutter assembly**




Hold the blades with a cloth. Unscrew the clutch counterclockwise.




Disassemble the new cutter assembly.




Align the groove in the bushing with the rib on the pitcher and press into place from inside the pitcher.




Install the pressure washer, tab washer, and retainer nut by hand. Do NOT overtighten the retainer nut!



Use a flathead screwdriver to bend up two opposing tabs on the tab washer.




Install the shaft and blades



Install the felt washer and clutch.



Tighten the clutch by turning it clockwise while holding the blades with a cloth.

 4421 Waterfront Drive Glen Allen, VA 23060	Revision Description:	Create New CARE Part			Rev. Date:
	Request #:	DOC10882	Page: 5 of 5	Document #:	03/23/2020
				540005800	Rev: D