



CAUTION: DISCONNECT POWER SUPPLY BEFORE SERVICING

THIS DRAWING AND PRINCIPLES OF DESIGN ARE NOT TO BE REPRODUCED, COPIED OR LOANED IN PART OR WHOLE WITHOUT THE WRITTEN CONSENT OF:
STOELTING
A Polar Ware Company
KIEL, WISCONSIN 53042

WIRING DIAGRAM - MODEL(S) COVERED:
U411-3812, DQU41-3812, U411-1812, DQU411-1812, U411-10212

DATE	DRAWN BY:	DWG. NO.	SHEET
4/21/2014	GB	2204611-WD	1 OF 1



CAUTION: DISCONNECT POWER SUPPLY BEFORE SERVICING

THIS DRAWING AND PRINCIPLES OF DESIGN ARE NOT TO BE REPRODUCED, COPIED OR LOANED IN PART OR WHOLE WITHOUT THE WRITTEN CONSENT OF:

STOELTING
A Polar Ware Company
KIEL, WISCONSIN 53042

WIRING DIAGRAM - MODEL(S) COVERED:			
U411-109I2I2, DQU41-109I2, U411-309I2, DQU411-309I2			
DATE	DRAWN BY:	DWG. NO.	SHEET
3/20/2014	GB	2204614-WD	1 OF 1