



WIRING DIAGRAM RT-5 ROTISSERIE 415/50/3

* A GREEN/YELLOW GND. WIRE MUST BE CONNECTED BETWEEN THE PART AND THE UNIT'S CHASSIS.




WIRING DIAGRAM RT-5 ROTISSERIE 380/50/3

⚡ A GREEN/YELLOW GND. STRAP MUST BE CONNECTED BETWEEN THE PART AND THE UNIT'S CHASSIS.




WIRING DIAGRAM RT-5 ROTISSERIE 230/50/1

⊛ A GREEN/YELLOW GND. STRAP MUST BE CONNECTED BETWEEN THE PART AND THE UNIT'S CHASSIS.



WIRING DIAGRAM RT-5 ROTISSERIE 208-240/60/3

Ⓜ A GREEN/YELLOW GND. STRAP MUST BE CONNECTED BETWEEN THE PART AND THE UNIT'S CHASSIS.



WIRING DIAGRAM RT-5 ROTISSERIE 208-240/60/1

Ⓜ A GREEN/YELLOW GND. STRAP MUST BE CONNECTED BETWEEN THE PART AND THE UNIT'S CHASSIS.

