



USER INTERFACE



356263-1
1-4 WELL HOT, COLD & FROZEN WIRING DIAGRAM




120/208 UNIT

WARNING!


REQUIRED NEMA 14-20R RECEPTACLE
MUST BE WIRED ACCORDINGLY OR
CONDENSING UNIT / AUXILIARY
COMPONENT DAMAGE WILL RESULT.
WARRANTY WILL BE VOID. TEST
RECEPTACLE PER THE FOLLOWING:

G, GROUND
X, LINE 1
Y, LINE 2
W, NEUTRAL



X-Y, 208-240V
X-W, 120V
Y-W, 120V

120/208 V




Busbar required
for 120V

120 V

DETAIL A


1-4 WELL HOT, COLD & FROZEN WIRING DIAGRAM



CONDENSING UNIT
UMX4121U

356263-1
1-4 WELL HOT, COLD & FROZEN WIRING DIAGRAM

CONDENSING UNIT CONTROL BOARD
FUNCTION FLOW CHART



RELAY CONTROL BOARD
FUNCTION FLOW CHART

- Initial condition
- Drain valve -Closed
 - Refrigerent line valve -Closed

